

OIL CONSERVATION DIVISION

P. O. BOX 208 **RECEIVED**

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	
LAND OFFICE	
OPERATOR	☒

APR 25 1983

O. C. D.

5a. Indicate Type of Lease

State ☐

Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER-	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Spool SU Com
3. Address of Operator 207 South 4th St., Artesia, NM 88210	9. Well No. 3
4. Location of Well UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM East LINE, SECTION 14 TOWNSHIP 7S RANGE 25E N.M.P.M.	10. Field and Pool, or Whident Pecos Slope Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3689.9' GR	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER Lost circulation plugs ☒

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Lost circulation at 1330'. Set lost circulation plugs as follows:

Plug #1: Tagged cement at 1361'. Spotted 50 sacks Thixolite, 10#/sack gilsonite, 1/2#/sack celloseal, 1#/sack Permacheck and 3% CaCl2. PD 6:00 PM 4-17-83. Plug set at 1355'. WOC 2 hours.

Plug #2: Tagged cement at 1355'. Spotted 50 sacks Thixolite, 10#/sack gilsonite, 1/2#/sack celloseal, 1#/sack Permacheck and 3% CaCl2. PD 8:15 PM 4-17-83. Plug set at 1350'. WOC 2 hours.

Plug #3: Tagged cement at 1340'. Spotted 50 sacks Thixolite, 10#/sack gilsonite, 1/2#/sack celloseal, 1#/sack Permacheck and 3% CaCl2. PD 10:30 PM 4-17-83. Plug set at 1335'. WOC 2 hours.

Plug #4: Tagged cement at 1280'. Spotted 50 sacks Thixolite, 10#/sack gilsonite, 1/2#/sack celloseal, 1#/sack Permacheck and 3% CaCl2. PD 12:30 AM 4-18-83. Plug set at 1275'. WOC 3 hours.

Plug #5: Tagged cement at 1225'. Spotted 50 sacks Thixolite, 10#/sack gilsonite, 1/2#/sack celloseal, 1#/sack Permacheck and 3% CaCl2. PD 3:45 AM 4-18-83. Plug set at 1220'. WOC 3 hours. TIH. Tagged cement at 1150'. Drilled out at 5:00 PM 4-18-83. Maintained full returns.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Leslie A. Clements

TITLE Production Supervisor

DATE 3-21-83

Original Signed by

Leslie A. Clements

APR 27 1983

APPROVED BY _____

TITLE Supervisor District II

DATE _____

CONDITIONS OF APPROVAL, IF ANY: