

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

RECEIVED

Form C-103
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	☒
LAND OFFICE	☒
OPERATOR	☒

APR 21 1983

O. C. D.

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER ☐

Name of Operator

Yates Petroleum Corporation ☒

Address of Operator

207 South 4th St., Artesia, NM 88210

Location of Well

UNIT LETTER 1 1980 FEET FROM THE South LINE AND 660 FEET FROM
THE East LINE, SECTION 14 TOWNSHIP 7S RANGE 25E NMPM.

5a. Indicate Type of Lease

State ☐

Fed ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name

Spool SU Com

9. Well No.

3

10. Field and Pool, or Wildcat

Pecos Slope Abo

15. Elevation (Show whether DF, RT, GR, etc.)
3689.9' GR

12. County
Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNS. ☒

PLUG AND ABANDONMENT ☐

REPAIR OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOB ☒

OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 14-3/4" hole 9:00 PM 4-14-83. Set 40' of 20" conductor pipe. Ran 21 joints of 10-3/4" 40.5# J-55 casing set 844'. 1-Texas Pattern notched guide shoe set 844'. Insert float set 803'. Cemented w/400 sacks Pacesetter Lite, 3% CaCl2. Tailed in w/300 sacks Class "C" 2% CaCl2. Compressive strength of cement - 1250 psi in 12 hours. PD 8:30 AM 4-16-83. Bumped plug to 800 psi, released pressure and float held okay. Cement circulated 50 sacks. WOC. Drilled out 2:30 AM 4-17-83. WOC 18 hours. Nipped up and tested to 1000 psi for 30 minutes, okay. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Leslie A. Clements

TITLE Production Supervisor

DATE 4-19-83

Original Signed By

Leslie A. Clements

Supervisor District II

APPROVED BY

TITLE

DATE

APR 27 1983

CONDITIONS OF APPROVAL, IF ANY: