

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NM OIL CONS. COMMISSION
Drawer DD
Artesia, NM 88210

Form Approved.
Budget Bureau No. 42-R1424

45F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

RECEIVED

1. oil ☐ well gas ☒ well other ☐

FEB 08 1983

2. NAME OF OPERATOR
Yates Petroleum Corporation

O.C.D.

3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210

ARTESIA OFFICE

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980 FNL & 1980 FEL, Sec. 9-6S-25E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

☒
☐
☐
☐
☐
☐
☐
☐

5. LEASE

NM 19416

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Langley RJ Federal

9. WELL NO.

4

10. FIELD OR WILDCAT NAME
Pecos Slope Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Unit G, Sec. 9-T6S-R25E

12. COUNTY OR PARISH
Chaves

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
4008' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 14-3/4" hole 2:30 PM 1-24-83. Ran 22 jts of 10-3/4" 40.5# casing set at 925'. 1-Texas Pattern notched guide shoe set at 925'. Insert float set 885'. Cemented w/400 sacks Pacesetter Lite, 3% CaCl₂, 1/4# celloseal. Tailed in w/300 sacks Class "C" w/2% CaCl₂. Compressive strength of cement - 1250 psi in 12 hours. PD 2:30 AM 1-26-83. Bumped plug to 1000 psi, released pressure and float held okay. WOC. Drilled out 9:30 PM 1-26-83. WOC 19 hours. Nipped up and tested to 1000 psi for 30 minutes. okay. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

Production

SIGNED _____ TITLE Supervisor DATE 1-28-83

APPROVED BY _____
CONDITIONS OF APPROVAL IF ANY:

ACCEPTED FOR RECORD (This space for Federal or State office use)
(ORIG. SGD.) DAVID R. GLASS

FEB 04 1983

MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

RECEIVED
FEB 2 1983

MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO