Form 9-331 Dec. 1973 UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	S. COMMISSIUM Form Approved. Budget Bureau No. 42-R1424 88210SE NM 16091 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME RECEIVED
1. oil gas well 🕅 well other	Boaz WO Federal FEB 0 8 1983 9. WELL NO.
2. NAME OF OPERATOR	1 O. C. D.
Yates Petroleum Corporation / 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME ^{ARTESIA} , OFFICE
207 South 4th St., Artesia, NM 88210 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.) AT SURFACE: 1650 FSL & 330 FEL, Sec. 10-5S-27E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Unit H, Sec. 10-T5S-R27E 12. COUNTY OR PARISH 13. STATE Chaves NM 14. API NO
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3957 ', I GR
TEST WATER SHUT-OFF X FRACTURE TREAT X SHOOT OR ACIDIZE X REPAIR WELL X PULL OR ALTER CASING X MULTIPLE COMPLETE X CHANGE ZONES X ABANDON* X (other) X	(NOTE: Report results of multiple completion or zone change on Form 9–330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
Spudded a 17-1/2" hole 9:15 AM 1-30-83. Set 40' of 20" conductor pipe. Ran 9 joints

Spudded a 17-1/2" hole 9:15 AM 1-30-83. Set 40' of 20" conductor pipe. Ran 9 joints of 13-3/4" 54.5# H-40 ST&C casing set at 342'. 1-Texas Pattern notched guide shoe set 342'. Insert float set 299'. Cemented w/375 sacks Class "C" 2% CaCl2. Compressive strength of cement - 1250 psi in 12 hours. PD 9:30 PM 1-30-83. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 50 sacks. WOC. Drilled out 3:30 PM 1-31-83. WOC 18 hours. Nippled up and tested to 1000 psi, okay. Reduced hole to 12-1/4". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type		Set @ Ft.
18. I hereby certify that the foregoing is true and correct		
SIGNED CORPECTED FOR RECORD SUPERVISOR	DATE	2-1-83
APPROVED BY CONDITIONS OF APPROVAE BY (ORIG. SGD.) DAVID R. GLASS TTLE	DATE	REEVED
MINERALS MANAGEMENT SERVICE ROSWELL, NEW MEXICO *See Instructions on Reverse Side		FEB 2 1983
a a a company a structure a state of the state		ON A COS MINERALS COMMT. SERVICE ROSWELL, NEW MEXICO

.....