ITH OIL CONS. COMMISSION

Dromer DD

Artesia, NM 88210

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

5.	LEASE	NM	28305	
6.	IF INDIAN	, ALL	OTTEE OR TRIBE NAME	
 7	LINIT ACP	 F E M :	ENT NAME	RECEIVED

7. UNIT AGREEMENT NAME

CHMDDV	MOTICES	ANID	REPORTS	ON	WELLO
SUNDRI	NULLES	AIND	REPURIS	UN	MELLO

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil gas \mathcal{K} well well other

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR 207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980 FSL & 660 FEL, Sec.24-7S-25E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)

SUBSEQUENT REPORT OF:

MAR 08 1983 8. FARM OR LEASE NAME Binnion TT Federal 9. WELL NO. ARTESIA, OFFICE 10. FIELD OR WILDCAT NAME Pecos Slope Aho


11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit I, Sec. 24-T7S-R25E

12. COUNTY OR PARISH 13. STATE Chaves NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD) 3627 **'.1**GR



OIL & GAS MINERALS MGMT. SERVICE

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and per

Spudded a 14-3/4" hole 9:30 PM 2-26-83. Ran 23 joints 10-3/4" 40.5# J-55 ST&C casing set 850'. 1-Type "M" notched guide shoe set 850'. Insert float set 810'. Cemented w/400 sacks Halliburton Lite, 1/4#/sack flocele and 2% CaCl2. Tailed in w/250 sacks Class "C" 2% CaCl2. Compressive strength of cement - 1250 psi in 12 hours. PD 1:45AM 2-28-83. Bumped plug to 750 psi, released pressure and float held okay. Cement circulated 50 sacks. WOC. Drilled out 7:45 PM 2-28-83. WOC 18 hours. Nippled up and tested to 1000 psi for 30 minutes, okay. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type			
18. I hereby certify that the foregoing is true and correct			
SIGNED La Contraction Supervisor	DATE3-2-83		
(ORIG. SGD.) DAVID R. GLASS			
CONDITIONS OF APPROMINE ANT 1983	DATE		
MAR 0 7 1983			
MINITAMS MANAGEMENT STRVICE			
ROSCIOCIO MEM MECICO LISTRICTIONS ON Reverse Side			