Form 9-331 Dec. 1973	NH OFL COFS, C Drawor PD Artepia, NH 8	Form Approve	С/В 'Ф d. J No. 42-R1424
UNITED STAT DEPARTMENT OF THE GEOLOGICAL SU	ES INTERIOR	5. LEASE NM 18607 6. IF INDIAN, ALLOTTEE OR TRI	•
SUNDRY NOTICES AND REA (Do not use this form for proposals to drill or to d reservoir. Use Form 9-331-C for such proposals.)		 7. UNIT AGREEMENT NAMÉ 8. FARM OR LEASE NAME Rita TZ Federal 	RECEIVED APR 1 8 1983
 well Ll well Xl other NAME OF OPERATOR Yates Petroleum Corporation ADDRESS OF CPERATOR 	1	9. WELL NO. 2 10. FIELD OR WILDCAT NAME - Und. Pecos Slope Abo	O. C. D. ARTESIA, OFFICE
 207 South 4th St., Artesia, 4. LOCATION OF WELL (REPORT LOCATI below.) AT SURFACE: 1980 FSL & 1980 AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 	ON CLEARLY. See space 17	<pre>11. SEC., T., R., M., OR BLK. AN AREA Unit K, Sec. 4-T8S-R2 12. COUNTY OR PARISH 13. S Chaves NM 14. APL NO.</pre>	D SURVEY OR 6E FATE
16. CHECK APPROPRIATE BOX TO INDIC REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSECTION SHOOT OR ACIDIZE	BSEQUENT REPORT OF:	14. APT NO. 15. ELEVATIONS (SHOW DF, KI 3741.4' GR	DB, AND WD)
REPAIR WELL [] PULL OR ALTER CASING [] MULTIPLE COMPLETE [] CHANGE ZONES [] ABANDON* [] (other)	MINERALS M	(NOTE: Report résults of multiple con 7 1983 change on Form 9–330.) 8 0.3 0137, SERVIDE NEW MEXICO	mpletion or zone
 DESCRIBE PROPOSED OR COMPLETE including estimated date of starting ar measured and true vertical depths for a h h 1/2 2//15 - 2 20 mm 	D OPERATIONS (Clearly state by proposed work. If well is d all markers and zones pertinen	e all pertinent details, and give period irectionally drilled, give subsurface t to this work.)*	locations and
Spudded 14-3/4" hole 3:30 PM	3-31-83. Set 40' of	£ 20" conductor pipe.	Ran 27 jts

10-3/4" 40.5# J-55 ST&C casing set at 1087'. 1-Texas Pattern notched guide shoe set at 1087'. Insert float set at 1046'. Cemented w/500 sacks Pacesetter Lite 3% CaCl2. Tailed in w/300 sacks Class "C" 2% CaCl2. Compressive strength of cement - 1250 psi in 12 hours. PD 3:15 AM 4-3-83. Bumped plug to 750 psi, released pressure and float held okay. Cement circulated 50 sacks. Drilled out 9:15 PM 4-3-83. WOC 18 hours. Nippled up and tested to 1000 psi for 30 minutes, okay. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

References -

Subsurface Safety Valve: Manu. and Type Set @ Ft.	
18. Thereby certify that the foregoing is true and correct Production SIGNED <u>La contact and correct</u> DATE <u>4-6-83</u>	<mark>8</mark>
ACCEPTED FOR RECORDs space for Federal or State office use) (ORIG. SGD.) DAVID R. GLASS CONDITIONS OF APPROVAPR 15 1983	2000 - 2
ROSWELL, NEW MEXICO *See Instructions on Reverse Side	