```
Γ-8-S, R-27-E, N.M.P.M.
Chaves County, New Mexico
(2175' San Andres Test)
            Building Location - WOCT
1/20/82
            RUCT, Spud 3:30 P.M. Drilling 10' (H & J Drilling Company)
1/21/82
                                                                                RECEIVED
            Drilling @ 45'
1/22/82
                                                                             JUN 20 1983
            Drilling @ 80'
1/23/82
            Drilling @ 170'
                                                                              O. C. D.
'/25/82
                                                                            ARTESIA, OFFICE
            Drilling @ 230'
'/27/82
         ➤ Drilling @ 270; Water 190-215, Bailed Dry.
'/28/82
            Depth @ 270' Cleaning out @ 265'; Loaded hole with gravel to straighten.
1/29/82
'/30/82
           Drilling @ 285'; Anhydrite
           Drilling @ 300'
/2/82
           Drilling @ 315'
/3/82
           Drilling @ 330'; Grey Sand
3/4/82
           TD 345' WOC; Ran 8 5/8" casing to 345 cemented with 200 sx., circulated
/5/82
           Drilling @ 360'
/6/82
           Drilling @ 390'
/7/82
/9/82
           Drilling @ 465!
           Drilling @ 465'; Shut down, rig repair
/10/82
           Drilling @ 470'; Anhydrite
/11/82
           Drilling @ 510'; Anhydrite
/12/82
           Drilling @ 555'
/13/82
           Drilling @ 600'; Salt and Anhydrite
/14/82
           Drilling @ 650'; Anhydrite
/16/82
           Drilling @ 685'; Anhydrite
/17/82
           Drilling @ 710'
/18/82
/19/82
           Drilling @ 765'
           Drilling @ 810'
/20/82
           Drilling @ 850'; Anhydrite and Shale
/21/82
```

Drilling @ 885'; Anhydrite and Shale

/23/82

CARL A. SCHELLINGER

Campbell Station Unit No. 2 560' FSL & 560' FWL Sec. 34,