

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐
2. NAME OF OPERATOR
Yates Petroleum Corporation
3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 2248' FSL & 1989' FEL, Sec.6-7S-26E
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☒
☐
☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE
NM 2359
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Sorenson IB Federal
9. WELL NO.
4
10. FIELD OR WILDCAT NAME
Pecos Slope Abo
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Unit J, Sec. 6-T7S-R26E
12. COUNTY OR PARISH
Chaves
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3651.4' GR

RECEIVED BY

DEC 13 1983

O. C. D.

ARTESIA, OFFICE

RECEIVED
NOV 29 10 43 AM '83
BUREAU OF LAND MGMT
ROSWELL DISTRICT

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 14-3/4" hole 6:45 PM 11-19-83. Ran 23 jts of 10-3/4" 40.5# J-55 ST&C casing set 907'. 1-Texas Pattern notched guide shoe set 907'. Insert float set 868'. Cemented w/400 sacks Pacesetter Lite 2% CaCl2. Tailed in w/300 sacks Class "C" 2% CaCl2. Compressive strength of cement - 1250 psi in 12 hrs. PD 4:35 PM 11-21-83. Bumped plug to 1000 psi, released pressure and float held okay. Cement did not circulate. WOC 6 hrs. Ran Temperature Survey and found top of cement at 590'. Ran 1". Tagged cement 590'. Spotted 250 sacks Class "C" 2% CaCl2. PD 3:00 AM 11-22-83. Cement circulated 20 sacks. WOC. Drilled out 4:45 PM 11-22-83. WOC 24 hrs and 10 min. Nippled up and tested to 1000 psi, for 30 minutes, OK. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED David R. Glass TITLE Production Supervisor

DATE 11-23-83

ACCEPTED FOR RECORD (space for Federal or State office use)

APPROVED BY (ORIG. SGD.) DAVID R. GLASS
CONDITIONS OF APPROVAL DEC 12 1983

DATE

ROSWELL, NEW MEXICO

*See Instructions on Reverse Side