


ORLA PETCO, INC.



P. O. BOX 1383, MIDLAND, TEXAS 79702
TELEPHONE 915 684-4762

Call Mitchell Energy - 682-5396 (Beth)
Gulf/Scouting Unit - 685-4679-687-7220
Suzanne

ORLA PETCO, INC. - GULF-STATE NO. 1

LOCATION: SW/4 SE/4 of Section 14, T-14-S, R-29-E, Chaves County, NM
Field: Double L - Queen Unit 1980' FEL and 660' FSL
Contractor: Hopi Drilling Co.
Depth: 1900'

11/7/83	Moved in rig. Shut down for rain. Prep to rig up.
11/8/83	Waiting on location to dry from rains.
11/9/83	Rigging up. Spud @ 2 p.m. on 8th. Started running tower ⁵ ing on Wed.
11/12/83	Ran 8-5/8" surface pipe to 300'. Cemented with 100 sx, circulated 20 sx to pit.
11/14/83	350' Drilling in Red Bed and broken Anhydrite.
11/15/83	495' Drilling in Salt.
11/16/83	570' Salt. Broken down from evening on. Waiting on transmission repairs.
11/17/83	570' Waiting on rig repairs
11/18/83	680' Drilling in Salt.
11/21/83	1050' Drilling in Lime.
11/22/83	1140' Drilling in Red Shale with lots of sand and small amount of gyp. Sand cutting into bits.
11/23/83	1250' Drilling in Red Shale with lots of sand texture; went through some Anhydrite .
11/28/83	1575' Fishing. Anhydrite.
11/29/83	1660' Dark Red Sand and gravel--it is water bearing. Picked up water between 1623 and 1639'. Making approximately 2 to 3 bailers in 2 hrs. Drilling.
11/30/83	1765' Drilling in Anhydrite. Very likely to drill in late this evening or early in the morning.
12/1/83	1797' Shale & Anhydrite 90%, Gray & Red Sand 10%. Geologist thinks they are at the top of Queen. SD at 7 p.m. Started up this a.m. and cleaned out hole. Started drilling at 1797'.