

NM OIL COND. ...
Driller DD
Artesia, NM 88210

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form Approved.
Budget Bureau No. 42-R1424

RECEIVED BY
JAN 12 1984 NM 51830
O. C. D.
ARTESIA, NM OFFICE

C/S 7

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other

2. NAME OF OPERATOR
Yates Petroleum Corporation

3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
2180 FSL & 1980 FEL, Sec. 1-7S-25E
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

5. LEASE
NM 51830

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
O. C. D.

7. OFFICE AGREEMENT NAME
ARTESIA, NM OFFICE

8. FARM OR LEASE NAME
Ruth XK Federal

9. WELL NO.
1

10. FIELD OR WILDCAT NAME
Pecos Slope Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Unit J, Sec. 1-T7S-R25E

12. COUNTY OR PARISH | 13. STATE
Chaves | NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3679' GR

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input checked="" type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <input type="checkbox"/>	<input type="checkbox"/>

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED
JAN 9 10 33 AM '84
BUR. OF THE MOUNT
ROSWELL DISTRICT

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 14-3/4" hole 4:30 PM 12-31-83. Ran 20 joints of 10-3/4" 40.5# J-55 casing set 841'. 1-Texas Pattern notched guide shoe set 841'. Insert float set 801'. Cemented w/300 sacks Pacesetter Lite 3% CaCl2. Tailed in w/250 sacks Class "C" 2% CaCl2. Compressive strength of cement - 1250 psi in 12 hrs. PD 6:00 AM 1-2-84. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 30 sacks. WOC. Drilled out 12:00 AM 1-3-84. WOC 18 hours. NU and tested to 1000 psi for 30 minutes, OK. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct
SIGNED [Signature] TITLE Production Supervisor DATE 1-4-84

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
[Signature]
JAN 10 1984

*See Instructions on Reverse Side