

C/8/77

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

RECEIVED BY  
JUN 05 1984  
O. C. D.  
ARTESIA, OFFICE

5. LEASE  
NM 0223201

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
N/A

7. UNIT AGREEMENT NAME  
N/A

8. FARM OR LEASE NAME  
Lura Federal

9. WELL NO.  
#2

10. FIELD OR WILDCAT NAME  
Sams Ranch *Grayburg*

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA  
Sec. 9, T14S, R28E

12. COUNTY OR PARISH | 13. STATE  
Chaves | New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3578' GR

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331 C for such proposals.)

1. oil well  gas well  other
2. NAME OF OPERATOR  
Herman V. Wallis
3. ADDRESS OF OPERATOR  
140 Pleasant View Dr., Kerrville, Texas 78028
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1980' FNL & 660 FEL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input checked="" type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <input type="checkbox"/>	<input type="checkbox"/>

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

JUN 1 1984

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spud 12 1/4" hole @ 2:45 PM MST 5-24-84.  
 Surface TD @ 9:20 PM MST 5-24-84  
 Ran 8 jts. (264') 8 5/8", 24#. J-55, R-2, new casing.  
 Set & cemented with 5- sx Class C, 2% CaCl.  
 Circulate 5 sx good cement to surface.  
 Bump plug with 650 psi @ 1:35 AM MST 5-25-84.  
 Plug held.  
 WOC 14 hours.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *Herman V Wallis* TITLE Operator DATE 5-29-84

ACCEPTED FOR RECORD (This space for Federal or State office use)

APPROVED BY PETER W. CHESTER TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL IF ANY

JUN 4 1984

\*See Instructions on Reverse Side