

Operator McKay Oil Corp <sup>SUP</sup> Date Received/Logged 5 Jan 87  
 Well Name #8 Four m. E. Franked Map Number D-14  
 Surface Owner Federal Allottee & Allotment # Franken 4010  
 Field Inspected C. D. Gale 6 Jan 87 W.D. McKnight  
 Name Date

	Yes	No		Yes	No
1. Arch Report Received			8. Resource Sign Off	✓	
2. Arch Report Matches SUP Map	✓		9. Appropriate Stips Checked	✓	
3. Field Checked (Arch Problems)	✓		10. Sensitive Area Conflicts		✓
4. Owner/Operator Agreement		✓	11. Caliche Pit Identified	N/A	
5. Allottee Map & Letter Sent	✓		12. Arch Clearance on Pit/ Pit File		
6. Road & Pad on Master Map	✓		13. Compliance Cards Filed		
7. Pictures In File			14. Approved APD same as SUP		
			15. Is SUP within three hundred ft. of a major R/W corridor?		✓

Field Checklist			Yes	No
16. Road or pad requires caliche				
17. Road or pad conflicts with livestock waters, feeding areas, corrals, etc.				
18. Can road be coordinated with future pipelines				
19. Road or pad requires major earthwork (side cuts etc.)				
20. Fences crossed				
21. Pad or road within 200 feet of cliff face or identified raptor nest				
22. Would road or pad remove any trees				
23. Road or pad within 200 feet of any permanent water (natural)				
24. Road or pad within 200 feet of riparian vegetation				
25. Road or pad within 200 feet of cave or sink hole				
26. Does there appear to be any cultural resources within road or pad				
27. Does Arch report match field stakes				
28. Does SUP map match field stakes		not well drawn		
29. Road or pad within a flood plain				
30. Will road or pad create excessive visual intrusion				
31. Pictures of road & pad				
32. Identified caliche pit suitable				
33. If field inspected before SUP arrives, has location & road been mapped				
Remarks				

no road crossing (except on pad) Early morning - very white fog  
 to see, grass, grass, scattered, mounds, fields, grass, cholla