

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NM Oil Cons. Commission
SUBMIT IN TR. LOCATE
Driller, DP
Artesia, NM 88210

Form approved.
Budget Bureau No. 1004-1
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	RECEIVED AUG 12 1991 O. C. D. ARTESIA OFFICE	5. LEASE DESIGNATION AND SERIAL NM-36193
2. NAME OF OPERATOR McKay Oil Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Post Office Box 2014, Roswell, New Mexico		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 1980' FEL		8. FARM OR LEASE NAME Four Mile Draw Fed
		9. WELL NO. #9
		10. FIELD AND POOL OR WILDCAT W. Pecos Slope Abo
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17-6S-22E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4340' GL	12. COUNTY OR PARISH Chaves
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data


NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	Run pipe	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Run pipeline on well North by Northeast as shown on exhibit "A"

2" steel pipeline will be buried approximately 12" from the surface

This route has been surveyed by Archaeological Survey Consultants



18. I hereby certify that the foregoing is true and correct

SIGNED Theresa Rodriguez TITLE Production Analyst DATE July 24, 1991

(This space for Federal or State office use)

APPROVED BY /s/ Becky Moore TITLE Acting DATE AUG 9 1991

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

5031 IV SE
(ROUND MOUNTAIN SE) MC DANIELS

EXHIBIT "A"

