, a	1 24 : 1	C		IV.CXICO	
ENERGY	AND	MIN	<b>ERALS</b>	DEPARTME	NT

48. 97 COPIED RECEIVED	1	
DISTRIBUTION	-	
SANTA FE	17	
FILE	Ŀ	
U.S.G.S.	<u>L</u>	
LAND OFFICE	<u> </u>	l
	T	T —

Spotted 50 sx Class (Drilled out 3:00 AM 30 mintues, OK. Redu	n above is true and complete to the best	illed plug and resumed d	sted to 1000 psi for
Spotted 50 sx Class (Drilled out 3:00 AM 30 mintues, OK. Redu	uced hole to 7-7/8". Dr	illed plug and resumed d	sted to 1000 psi for
Spotted 50 sx Class (Drilled out 3:00 AM 30 mintues, OK. Redu	uced hole to 7-7/8". Dr	illed plug and resumed d	sted to 1000 psi for
Spotted 50 sx Class (Drilled out 3:00 AM	10-22-87. WOC 20 hrs a uced hole to 7-7/8". Dr	nd 30 minutes. NU and te illed plug and resumed d	sted to 1000 psi for
Spotted 50 sx Class Orilled out 3:00 AM	10-22-87. WOC 20 hrs a uced hole to 7-7/8". Dr	nd 30 minutes. NU and te illed plug and resumed d	sted to 1000 psi for
of spud. Resumed dr Ran 22 joints 9-5/8" set 910'. Insert fi 10# Gilsonite and 3% CaCl (yield 1.32, wei pressure and float he Survey and found top + 4% Cacl2. PD 2:00 Class C + 4% CaCl2.	at 9:15 AM 10-18-87. No rilling 5:00 PM 10-19-87 36# J-55 ST&C casing seloat set 869'. Cemented CaCl (yield 1.84, weigh ight 14.8). PD 6:30 AM eld okay. Cement did no of cement at 570'. Ran PM 10-21-87. WOC 1 hr. PD 3:15 PM 10-21-87. WaCl2. PD 4:30 PM 10-21-C + 4% CaCl2. PD 6:15 PM	Lost returns at 60'. t at 910'. 1-Texas Patt w/150 sx Halliburton Li t 12.8). Tailed in w/20 10-21-87. Bumped plug t circulate. WOC 6 hrs. 1". Tagged cement 510'. Ran 1". Tagged cement 0C 1 hr. Ran 1". Tagge 87. WOC 1-1/4 hrs. Ran M 10-21-87. Circulated	Regained returns. ern notched guide te w/1/4#/sx Flocele, 0 sx Class C + 2% o 500 psi, released Ran Temperature Spotted 50 sx Class C 320'. Spotted 50 sx d eement 160'. Spotted 1". Tagged cement 60' 5 sx to pit. WOC.
	perations (Clearly state all pertinent de	tails, and give pertinent dates, including	g estimated date of starting any propos
ULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JQS X	
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK COMMENCE ORILLING OPHS.	ALTERING CASING PLUG AND ABANDONMENT
	Appropriate Box To Indicate I	-	her Data T REPORT <b>O</b> F:
	12. County Chaves		
THE West LINE, SECTION			
Location of Well  UNIT LETTERN	West Pecos Slope Abo		
Address of Operaior 105 South 4th St.,	4		
Yates Petroleum Co	China Draw AEP State		
Name of Operator	OTHER-		8. Farm or Lease Name
OIL GAS T	7. Unit Agreement Name		
SUNDR			
OPERATOR	]	ARTESIA, OFFICE	5, State Oil & Gas Lease No.  LG 9575
		O. C. D.	State X Fee
U.S.G.S.	SANTA FE, NEW	Sa. Indicate Type of Lease	
LAND OFFICE			Revised 10-1-