

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THIS CATEGORY*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

Copy to B.F.

5. LEASE DESIGNATION AND SERIAL NO.

NM-8831

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

-

7. UNIT AGREEMENT NAME

-

8. FARM OR LEASE NAME

Federal (USA) 'F' NCT-1

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 30, T-18-S, R-10-E

12. COUNTY OR PARISH

Otero

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
TEXACO Inc.

3. ADDRESS OF OPERATOR
P.O. Box 728, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface
1980' FSL and 1980' FEL, Sec. 30, T-18-S, R-10-E

14. PERMIT NO.
Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4043' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(Other)

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TOTAL DEPTH 2455'

20" OD 78.60# casing set at 383'

Ran 2429' (74 joints) 13-3/8" OD 48#, 54.5# and 61# casing and cemented at 2455' with 2400 sx TLW w/ 5# gilsonite/sk, followed by 200 sx Class C. Cement circulated. Plug at 2414'. Job complete 1:00 PM, September 25, 1970.

Tested 13-3/8" OD casing with 1500# for 30 minutes from 7:00 AM to 7:30 AM, September 26, 1970. Tested OK. Drilled out plug. Retested w/600# for 30 minutes from 9:30 AM to 10:00 AM, September 26, 1970. Tested OK. Job complete 10:00 AM, September 26, 1970.

Received verbal permission to change plans from USGS at 10:00 AM, September 24, 1970.

RECEIVED
SEP 30 1970
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

Assistant District Superintendent

DATE

September 29, 1970

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

RECEIVED

ACCEPTED FOR RECORD PURPOSES
SEP 30 1970

Date

ACTING

District Engineer

*See Instructions on Reverse Side

APR 23 1971

U. S. G. C. OFFICE