

For
COPY ~~BE~~ C. C.

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa Fe
Lease No. 88-1036
Unit Pine

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 11, 1952

Well No. 1 is located 2081.9 ft. from S line and 1937.2 ft. from E line of sec. 19

19 (Sec. and Sec. No.) 19S (Twp.) 17E (Range) (Meridian)
Wildcat (Field) Chaves (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6546 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Will spot 50' cement plug 230'-150', spot 10' cement plug outside 16" casing and pour 32" x 32" x 12" pad over well with 4" x 6' pipe as marker. We will leave 142' of 16" casing in hole.

Note: This well has previously been temporarily abandoned and will now be a permanent abandonment.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Sun Oil CompanyAddress Box 2772Odessa, TexasBy C. S. AtkinsonTitle Superintendent