

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. FM-0415
Unit Pinon

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHUTTING IN WELL
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

2-19-, 19 52

Well No. 2 is located 660 ft. from N line and 660 ft. from W line of sec. 20
N 1/4 - N 1/4 sec 20 19S 17E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox Chaves New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Filled hole with dirt from total depth of 1659' to 20' of top of hole, placed 20' plug to surface and placed 32" x 32" x 12" pad on surface with 4" x 6" pipe for marker and well is permanently abandoned.

U. S. GEOLOGICAL SURVEY
RECEIVED
FEB 21 1952
ARTESIAL DIVISION

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Oil Company
Address Box 2792
Odessa, Texas
By A. D. Wright
Title Superintendent