

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office LCLease No. 061614

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 13, 1953Well No. 1-Hopp is located 1730 ft. from N line and 1900 ft. from E line of sec. 28SW/4 NE/4 28
(1/4 Sec. and Sec. No.)158
(Twp.)28N
(Range)T.M.P.M.
(Meridian)Wildcat
(Field)Chaves
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 3241 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well has been completely abandoned as a dry hole by pulling 1476.89 feet of 9-5/8" intermediate casing, placing 18 sacks of cement plug 1469 - 1495, leaving hole filled with heavy mud and placing regulation surface marker cemented with 10 sacks cement.

We cleaned up the location and returned the surface to its original contour March 14, 1953.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Westcoast Hydrocarbons, Inc.Address P. O. Box 660Roswell, New MexicoBy Burton VotatoTitle Geological Engineer