

GEOLOGICAL SURVEY WELL STATUS REPORT

(To be submitted in quintuplicate on all inactive wells)

NAME AND ADDRESS OF OPERATOR

Dalport Oil Corporation ✓ 75202
3471 First National Bank Bldg. Dallas, Texas

WELL NO. AND LEASE NAME

1 Hill Federal

LEASE NO.

NM-061403-B

26

14-S

29-E

Footage Location of Well

1977 feet from South

1983 feet from West

Pool

Double L Queen Assoc.

COUNTY

Chaves

STATE

New Mexico

When Was Well Shut-in or Last Produced?

November 1975

RECEIVED

NOV 3 1976

Type Well

☐ Oil Well☒ Gas Well☐ Temp. Abd. Well

O.C.C.

ARTESIA, OFFICE

Producing Capability

BOPD

MCFGPD

1,147

BWPD

Date Last Tested 3/31/71

4. Is Well Considered Capable of Production in Paying Quantities?

☒ Yes☐ No

5. If Capable of Producing in Paying Quantities, Give Reasons For Not Producing Well.

Compressor has been down for repairs

RECEIVED

OCT 18 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

6. If Not Capable of Producing in Paying Quantities, Give Reasons For Not Plugging Well At This Time.

7. What Are Future Plans For Operating Well (Include Estimated Dates)?
Chala Cryogenics advises that they should have their compressor back in operation by January 1, 1977 and will commence taking gas at that time.

I hereby certify that the foregoing is true and correct

SIGNED

TITLE

President

DATE

10/14/76

(This space for Federal or State office use)

TITLE

DATE

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

U. S. GEOLOGICAL SURVEY
ACTING DISTRICT ENGINEER