

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Number 42-4254.1
Approval expires 12-31-58
LAS CRUCES

Land Office **069535**

Lease No. **11**

Unit **Formerly LC 062246**

SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|--|--|-------------------------------------|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF | |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR | <input checked="" type="checkbox"/> |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 11

1956

Well No. **Nullis #1** is located **660** ft. from **XX** line and **1980** ft. from **EX** line of sec. **21**
SE SW **21** **158** **29E** **100N**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Chaves **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

RECEIVED

The elevation of the derrick floor above sea level is _____ ft.

MAR 18 1966

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding, cementing points, and all other important proposed work)

ARTESIA, OFFICE

October 11, 1956:

This well was not cleaned out pursuant to our Notice of Intention to do so, filed on September 10, 1956. With the approval of Mr. Frost, it has this date been recapped and marker replaced at surface.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **E. J. McCURDY ET AL**


Address **c/o Juanita Denton**

Box 308

By _____

Artesia, New Mexico

Title **Production Superintendent**



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **069535**
Unit **N**
Formerly LC 062246

SUNDRY NOTICES AND REPORTS ON WELLS

| | | | |
|--|-------------------------------------|--|--|
| NOTICE OF INTENTION TO DRILL | | SUBSEQUENT REPORT OF WATER SHUT-OFF | |
| NOTICE OF INTENTION TO CHANGE PLANS | | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | <input checked="" type="checkbox"/> | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | | SUBSEQUENT REPORT OF ABANDONMENT | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Mullis **September 10**, 19**56**
Well No. **#1** is located **660** ft. from **[S]** line and **1980** ft. from **[W]** line of sec. **21**
SE SW 21 **15S** **29E** **101PM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Chaves **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth (Martin Yates, Jr. - Mullis #1) approximately 12,250 feet. Has now 3305 feet of 8-5/8" new and used casing.

Intend to clean out the well to the bottom of the casing, test with electric logs, perforate at base and squeeze with cement, and fracture production sections.

The above work is hereby approved subject to submission of a copy of the electric logs and surveys run upon completion of the above well, and please furnish this office with triplicate copies of form 9-331a "Sundry Notices and Reports on Wells", on any work done on the well and setting and cementing of casing.
I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **E. J. McCurdy et al** **U. S. Geological Survey**

Address **P. O. Box 183**
Artesia, New Mexico

By **E. B. Kenny**
Title **Production Superintendent**