

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

RECEIVED

FEB 20 1980

O. C. D.

SUNDRY NOTICES AND REPORTS ON WELLS, OFFICE

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REPERM OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

3a. Indicate Type of Lease

State ☐ Fee ☒

3. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name

Moots

9. Well No.

1

10. Field and Pool, or Wildcat

Wildcat

12. County

Chaves

Plugged & Abandoned Junked Hole

OIL WELL ☐ GAS WELL ☐

OTHER

2. Name of Operator

Rogers & Bryant Oil Company

3. Address of Operator

1001 8th Street, Levelland, Texas 79336

4. Location of Well

UNIT LETTER F 1980' FEET FROM THE North LINE AND 1980' FEET FROM
THE West LINE, SECTION 4 TOWNSHIP 15-S RANGE 25-E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

3565' DF (GL + 10')

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐PLUG AND ABANDON ☐
CHANGE PLANS ☐OTHER ☐REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- On 1/19/80, drilled 4th. cement plug fr. 6538 - 6600' (62'), losing complete returns. Mixed mud and LCM, regaining fairly complete returns in 3-3/4 hrs. Washed down to 6623'(our tally), tagging old TD, previously reported by Holmes & Ford at 6621' (drlr).
- Drilled new hole fr. 6623 to 6690' dol. & chert w/pyrite with fairly complete returns. MW 8.5 VIS 32 WL-NC w/LCM. At 6690', lost complete returns. Mixed mud and LCM w/o regaining returns. Did not DST lost circ. zone due to poor condition of rig, "green" crews and poor up hole conditions.
- Drilled new hole blind from 6690' to 6785' dol & cht w/o returns. At depth, 6785', attempted a trip for a new bit.(7:00PM 1/21/80). On 1/27/80, after going in hole with new bit and rewashed down to depth 5896', double pin sub between Bowen S-3 swivel and top tool joint box on 3-1/2" OD 15.50# Grade "G" drill pipe parted, losing bit, C-O sub, 9 6-1/2" OD drill collars and 180 jts. of 3-1/2" OD 15.50# grade "E" & "G" drill pipe in hole.
- From 1/28 - 1/31/80, fished for drill string. Drill string dropped to "bottom" TD 6785'. Fished and recovered 100-1/2 jts. of 3-1/2" OD 15.50# grade "E" & "G" drill pipe consisting of 85 straight jts. and 15-1/2 bent and corkscrewed jts.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

DATE

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: