

SUITE 314
PETROLEUM BUILDING

JACK L. MCCLELLAN
GEOLOGIST AND DRILLER
P. O. BOX 540
ROOSEVELT, NEW MEXICO 88201

SES 822-0215 3/7/69
SES 822-4590 4/2/69

JANUARY 6, 1969

RE: JACK L. MCCLELLAN
LISA "B" FEDERAL NO. 2
2201 FS & WL
SECTION 18-T15S-R30E
CHAVES COUNTY, NEW MEXICO

ATTACHMENT TO FORM 9-330

THE TEST SHOWN ON THIS REPORT WAS MADE IN OPEN HOLE BY A DRILLING TEST. DUE TO THE PRESENCE OF THIS WATER, THE WELL WILL NOT BE COMPLETED DUE TO THE DIFFICULTY OF DISPOSING OF THE WATER. THE PIPE IS FULL OF FRESH WATER AND A CULL PLUG HAS BEEN INSERTED IN THE 7" CASING.

THE WELL WILL EITHER BE COMPLETED AT A LATER DATE OR WILL BE DRILLED DEEPER TO TEST THE SAN ANDRES.

RECEIVED
JAN 10 1969
CHAVES COUNTY
NEW MEXICO