

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN DUPLICATE
(Other instructions on reverse side)

Form approved,
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0159536-C

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> DRILLING	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR PAN AMERICAN PETROLEUM CORPORATION	8. FARM OR LEASE NAME FEDERAL "C" GAS COM
3. ADDRESS OF OPERATOR BOX 68, HOBBS, N. M. 88240	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FNL x 1650' FWL Sec. 11 (Unit C, NE 1/4 NW 1/4)	10. FIELD AND POOL, OR WILDCAT BUFFALO VALLEY PENN- GAS
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 11-15-27 NMPM
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3493' RDB	12. COUNTY OR PARISH CHAUES
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 9-22-68, 8 5/8" OD 32" H-40 + J-55 casing was set @ 3236' w/ 1000 sy. Incon 4% Gel Salt Sat. w/ 2 1/2% PACL + 300 sy Incon neat 2% PACL. TCMT- 820'. After HOC 24 hours, tested casing w/ 2300 psi for 30 min. Test O.K. Reduced hole to 7 7/8" @ 3236' and resumed drilling.

RECEIVED
SEP 27 1968
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

SEP 25 1968

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL

TITLE

DATE

1- USGS-ART
1- NSW
1- SUSP
1- RRY
1- CITIES SERU

RECEIVED
SEP 27 1968
A. L. BURNHAM
ARTESIA DISTRICT ENGINEER

*See Instructions on Reverse Side