

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Water Injection Well APR 17 1981  
2. NAME OF OPERATOR  
McClellan Oil Corporation / O. C. D.  
3. ADDRESS OF OPERATOR  
Post Office Drawer 730, Roswell, New Mexico 88201 ARTESIA, OFFICE  
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
660' FNL & 2310' FWL

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3936' G.L.

5. LEASE DESIGNATION AND SERIAL NO.  
LC-069280-A  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT NAME  
Sulimar Queen Unit Tr. 1  
8. FARM OR LEASE NAME  
9. WELL NO.  
- 3  
10. FIELD AND POOL, OR WILDCAT  
Sulimar Queen  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 24-T15S-R29E  
12. COUNTY OR PARISH 13. STATE  
Chaves NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐  
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐  
SHOOT OR ACIDIZE ☐ ABANDON\* ☐  
REPAIR WELL ☐ CHANGE PLANS ☐  
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐  
FRACTURE TREATMENT ☐ ALTERING CASING ☐  
SHOOTING OR ACIDIZING ☐ ABANDONMENT\* ☐  
(Other) Convert to Water Injection ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

9/26/79: Ran 2-3/8" plastic lined tubing with packer set at 1958.07'. Annulus was filled with anti-corrosive packer fluid. Pressure gauge installed on tubing-casing annulus to check for tubing-annulus communications.

18. I hereby certify that the foregoing is true and correct

SIGNED Paul R. K. [Signature] TITLE Engineer DATE 4/14/81

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

ACCEPTED FOR RECORD

DATE

APR 16 1981

\*See Instructions on Reverse Side

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO