•	1N _e	• М. О. С. С. СОРУ,	Coping of 1
Form 9-331	U TED STATES	SUBMIT IN TR: STEEL OF COTHER CONTROL OF COTHER COT	Form approved. Budget Bureau No. 42-R1424.
(May 1963)	DEPARTMENT OF THE INTI	ERIOR (Other Instruction Constitution of the C	5. LRASE DESIGNATION AND BERIAL NO.
	GEOLOGICAL SURVEY	•	LC 069280-B
	DELL'ALORIGE AND DEDORT	C ON WELLC	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNI	DRY NOTICES AND REPORT	5 ON WELLS	
(Do not use tais i	form for proposals to drill or to deepen or p Use "APPLICATION FOR PERMIT—" for su	ich proposals.)	
1.			7. UNIT AGREGMENT NAME
WELL GAS WELL	XX OTHER DRY HOLE		
2. NAME OF OPERATOR			8. FARM OR LEASE NAME
JACK L. MCCLELLAN			LISA "B" FEDERAL
3. ADDRESS OF OPERATOR	0) 0	00001	9. WELL NO.
P. O. BOX 848, ROSWELL, NEW MEXICO, 88201 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			10. FIELD AND POOL, OR WILDCAT
See also space 17 belo	eport location clearly and in accordance with w.)	any State requirements.	and a
At surface			SULIMAR 11. SHC., T., R., M., OR BLK. AND
10001 501	. 6601 551		SURVEY OR AREA
1980' FSL	& 000' FEL		Sec. 13-T155-R29E
14. PERMIT NO.	15. ELEVATIONS (Show wheth	ner DF. RT. GR. etc.)	12. COUNTY OR PARISH 13. STATE
II, PERMIT NO.		L.	CHAVES NEW MEXICO
16.	Check Appropriate Box To Indica	ite Nature of Notice, Report, or	Other Data
N	OTICE OF INTENTION TO:	SUBSI	QUENT REPORT OF:
TEST WATER SHUT-OF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	BHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)	
(Other)		Completion or Recon	ts of multiple completion on Well apletion Report and Log form.)
17. DESCRIBE PROPOSED OR proposed work. If nent to this work.)	COMPLETED OPERATIONS (Clearly state all per well is directionally drilled, give subsurface	tinent details, and give pertinent date locations and measured and true vert	es, including estimated date of starting any ical depths for all markers and sones perti-
ON JUNE 10) AND JUNE 11, 1969, TH	IIS TEST WAS PLUGGED	AND ABANDONED AS
			•
FOLLOWS:			
			(01151)
HEAVY	MUD WAS PLACED IN THE	HOLE FROM TOTAL DE	EPTH (2115')
	A SPINSE 91	UG WAS SET AT 1210	ONE HUNDRED
TO FI	RST PLUG. A BRIDGE PL	UG WAS SET AT IZIO	. ONE HONDRED
	OF CEMENT DUMP-BAILED	ON TOP OF PLUG.	HOLF FILLED
+ E E I	OF CEMENT DOMP-BATEED	ON TOP OF FLOG.	
WITH	HEAVY MUD TO 500' AT W	WHICH DEPTH ANOTHER	BRIDGE PLUG
W 1 1 /1	HEAVI MOD TO JOO AT .		
WAS S	ET. 150' OF CEMENT WA	AS DUMP-BAILED. HI	EAVY MUD TO
SURFA	ICE, WITH A 201 PLUG AT	r surface. Marker :	SET AND CEMENTE
			RECEIVED.
24 HOUR TE	ST AT TOTAL DEPTH RECO	OVERED NO FLUID.	JUN 13 1969
			U. S. GEOLOGICAL SURVEY U. S. GEOLOGICAL SURVEY MEXICO
	•		OCUI OCICAL SOLICO
			U. S. GEOTT HEW MENIOR
	the longolog is true and correct		U. S. GEOLOGICAL SOLL ARTESIA, NEW MEXICO
18. I Reredy cercity that	8 911C CA 00	OPERATOR	DATE JUNE 12, 1969
SIGNED	TITLE	OFERATOR	DATE CONL 12, 1707
(This space for Fede	ral or State office use)		
TIT	= ()		P CON TAATTIN
A DOMENTIONS OF AL	PPROVAL, IF ANY:	R	ECMVED
4	./		•
B. Kul	200		FEB 1 9 10)
REKMA	*See Instruc	ctions on Reverse Side	
R. L. DL		w	D. C. S.
9			MATESIA, DEFICE