

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPL  
(Other instructions  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry		5. LEASE DESIGNATION AND SERIAL NO. NM 0555291
2. NAME OF OPERATOR McGrath & Smith, Inc. ✓		6. IF INDIAN, ALLOTTEE OR TRIBE NAME -----
3. ADDRESS OF OPERATOR 418 Building of Southwest, Midland, Texas 79701		7. UNIT AGREEMENT NAME -----
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  660' FSL and 1980' FWL		8. FARM OR LEASE NAME Keeler-Federal
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, CR, etc.) GL 3695 KB 3706		10. FIELD AND POOL, OR WILDCAT Wildcat
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17, T14S, R29E
		12. COUNTY OR PARISH Chaves
		13. STATE NM

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

## 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded 4:15 p.m., 9-13-70. 8 5/8" cmtd. at 251 with 150 sx. Circ. Drld. 7 7/8" hole to TD 2245' on 9-16-70. Cored Queen 1600-1632'. NS. Ran GR-Acoustic, LL, MLL logs. P & A as follows on 9-17-70. Spotted Class H cmt. plugs as follows:

30 sx. 1560-1660

30 sx. 675- 775

30 sx. 200- 300

10 sx. 0- 10 Top of 8 5/8" casg.

Installed cap and DHM on top of 8 5/8". P &amp; A complete at 3:45 p.m. 9-17-70.

Core was not analyzed.

## 18. I hereby certify that the foregoing is true and correct

SIGNED J. B. Taylor

TITLE

Supt.

DATE

9-18-70

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

SIGNATURES OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side