

215F

RECEIVED BY UNITED STATES DEPARTMENT OF THE INTERIOR  
MAY 07 1985 GEOLOGICAL SURVEY

### SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐  
2. NAME OF OPERATOR  
McClellan Oil Corporation ✓  
3. ADDRESS OF OPERATOR  
P.O. Drawer 730, Roswell, New Mexico 88202  
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1980' FNL & 1980' FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input checked="" type="checkbox"/>
(other)		

5. LEASE  
NM-27800  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
Jack Federal  
9. WELL NO.  
1  
10. FIELD OR WILDCAT NAME  
Wildcat  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 29-T15S-R29E  
12. COUNTY OR PARISH  
Chaves  
13. STATE  
NM  
14. API NO.  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3780' G.L.

(NOTE: Report results of multiple completion or zone changes on Form 9-330.)

SEP 11 1982

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

7/20/82: Plugged and Abandoned as follows:  
Spotted 30 sxs at 1750'. Tagged TOC @ 1500' after 4 hours  
Circulated hole with mud. Pulled 1284' of 5½" casing.  
Spotted 45 sxs at 1334'. Tagged TOC @ 1223'.  
Spotted 50 sxs at 365'. Tagged TOC @ 260'.  
Spotted 15 sx at surface. Installed dry hole marker.

Cleaned location and will level pit as soon as dry.

Post ID-2  
4-1-83  
Y+H

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Paul Ragsdale TITLE Operations Manager DATE September 9, 1982

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

APPROVED  
PETER W. CHESTER

MAY 3 1985

BUREAU OF LAND MANAGEMENT  
ROSWELL RESOURCE AREA