

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

copy to S. J.

Form approved.
Budget Bureau No. 42-B1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0493370-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

SULIMAR QUEEN UNIT

8. FARM OR LEASE NAME *Sulimar Queen*
TRACT *X* 5

9. WELL NO.

#3

10. FIELD AND POOL, OR WILDCAT

SULIMAR QUEEN

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 26-15S-29E-NMPM

12. COUNTY OR PARISH

CHAVES

13. STATE

NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
JACK L. MCCLELLAN

3. ADDRESS OF OPERATOR
Box 848 - ROSWELL, NEW MEXICO 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

2310' FSL & 2310' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3926.8 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SURFACE CASING

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

ON 6-7-72 RAN 8 5/8" OD 24# SH CSG TO 250'. DENTON OIL WELL CEMENTING CO. CEMENTED WITH 100 SKS CEMENT W/3% CACL.

ON 6-8-72 DRILLED PLUG AND WAITED 1/2 HOUR WITH NO WATER ENTRY. RESUMED DRILLING.

RECEIVED

JUN 19 1972

O. C. C.
ARTESIA, OFFICE

RECEIVED

JUN 14 1972

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

W. L. Gordon

TITLE

PRODUCTION

SUPERINTENDENT

DATE

JUNE 13, 1972

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED
JUN 16 1972
R. L. BECKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side