

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Copy to SF

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Harvey E. Yates Company, Inc.		8. FARM OR LEASE NAME East Lake Arthur Federal	
3. ADDRESS OF OPERATOR Suite 1000 Security National Bank Bldg., Roswell, N.M. 88201		9. WELL NO. #1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 1980' FWL		10. FIELD AND POOL, OR WILDCAT Wildcat <i>Strawn</i>	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 29, T-15S, R-27E	
15. ELEVATIONS (Show whether SF, ST, etc.) 2441' GL		12. COUNTY OR PARISH Chaves	
		13. STATE N.M.	

RECEIVED

MAR 31 1977

O. C. C.
ARTESIA OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

XX

FRACTURE TREAT

MULTIPLE COMPLETS

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

No economic reason to try completion of this well. We will plug and abandon as follows:

Plug #1 35 Sx Class H @ 5076' to 4976'
Plug #2 35 Sx Class H @ 3203' to 3103'
Plug #3 35 Sx Class H @ 1653' to 1553'
Plug #4 35 Sx Class H @ 60' to Surface - 9.5# per gal mud spotted between plugs.

RECEIVED

MAR 10 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *Paul G. Yates*

TITLE Vice President

DATE 3-4-77

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 30 1977

R. L. LEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side