

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

copy to SF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-1" for such proposals.)

1. NAME OF OPERATOR Harvey N. Yates Company, Inc. ✓		5. LEASE DESIGNATION AND NUMBER NM-7301	
2. ADDRESS OF OPERATOR Suite 1000 Security National Bank Building, Roswell, N.M.		6. IF INDIAN, ALLOTMENT OR TRACT NO. East Lake Archer Tract	
3. LOCATION OF WELL (Report location clearly and in accordance with any State or Federal survey. (See space 17 below.) 1980' FNL & 1980' FWL		7. UNIT ASSIGNMENT NO. #1	
4. PLANNING NO. 2441' GL		8. DATE OF LATEST REPORT Sec. 29, T-158, R-17E	
15. ELEVATIONS (Show whether DS, RT, GS, etc.) 2441' GL		9. WELL NO. Wildcat	
16. COUNTY OF PARRIS, NM STATE CHANDLER, N.M.		10. FIELD AND POOL OR WELLS Wildcat	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACTURE TREAT	☐	FRACTURE TREATMENT	☐
REPORT ON ACIDIZ	☐	REPORTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other)	☐
PULL OR ALTER CASING	☐	REPAIRING WELL	☐
MULTIPLE COMPLETE	☐	ALTERING CASING	☐
ABANDON*	☐	ABANDONMENT*	☐
CHANGE PLANS	☐		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of completion and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers also shown pertinent to this work.)*

2-28-77 Plugged and abandoned in the following manner:

Plug #1 35 Sx Class II @ 5076' to 4976'
 Plug #2 35 Sx Class II @ 3203' to 3103'
 Plug #3 35 Sx Class H @ 1653' to 1553'
 Plug #4 35 Sx Class H @ 60' to surface - 9.5# per gal mud spotted between plugs. Removed BOP and casing head. Welded a 1/4" steel plate over 8 5/8" casing stub and installed a 4 1/2" dry hole marker.

RECEIVED
MAR 30 1977
U.S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED _____	TITLE Vice President	DATE March 26, 1977
(This space for Federal or State office use)		
COPIES OF APPROVAL, IF ANY:	TITLE _____	DATE _____