

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN 'PLICATE*
(Other instr. as on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-2363

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		RECEIVED		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR		MAR 6 1973		8. FARM OR LEASE NAME	
Read & Stevens, Inc.				Langley "Com"	
3. ADDRESS OF OPERATOR				9. WELL NO.	
P. O. Box 2126, Roswell, New Mexico 88201		D. C. C.		1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State or Federal Survey or Area. See also space 17 below.) At surface		ARTESIA, OFFICE		10. FIELD AND POOL, OR WILDCAT	
990' FNL & 1650' FWL Sec. 13, T-15-S, R-27-E, N.M.P.M.				Buffalo Valley	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
		3601.1 GR -		Sec. 13-15S-27E, N.M.P.M.	
				12. COUNTY OR PARISH	
				Chaves	
				13. STATE	
				New Mexico	

13. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded well at 1:30 P.M., 2-15-73, drilled 17 1/2" hole to 306'.
Ran 7 joints of 12 3/4", 34#, F.W.P.S. casing, 306', set at 306'
RKB. Cemented with 300 sx. Class "C" cement with 2% CaCl₂. Plug
down at 2:15 A.M., 2-16-73. Circulated 25 sx. cement. WOC for 12
hours. Pressure tested to 500# for 30 min., held ok.

RECEIVED
MAR - 5 1973
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

John L. Anderson

TITLE Agent

DATE 2-19-73

(This space for Federal or State office use)

TITLE

DATE

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

MAR 5 - 1973

H. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side