DEPARTMENT OF THE INTERIOR SUBMIT IN TRI CAN DEPARTMENT OF THE INTERIOR verse side) GEOLOGICAL SURVEY

NOTICE OF INTENTION TO:

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

TEST WATER SHUT-OFF

FRACTURE TREAT

REPAIR WELL

SHOOT OR ACIDIZE

JATE.

Budget Bureau No. 42-R1424. AND SERIAL NO.

٠.	DEAD	DESIGNATION	٠

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

GEOLOGICAL SURVEY	NM-16114
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAM

	(Do not use this form for propos Use "APPLICA	als to drill or to deepen or plug back to hediterene reservoir. TION FOR PERMIT—" for such proposals.)	D
1.	OIL GAS X OTHER	OCT 3 1975	7. UNIT AGREEMENT NAME
2.	NAME OF OPERATOR		8. FARM OR LEASE NAME
	WOOD & COCKBURN,	INC. U.S.C.	Federal "B"
3.	ADDRESS OF OPERATOR	ARTESIA, OFFICE	9. WELL NO.
511 West Chio, Midland, Texas 79701 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit letter P Located 660 from the East line and 510 from the South line of Section 3.		1 10. FIELD AND POOL, OR WILDCAT Und. Double L. Queen Associations of Area Sec., T., E., M., OR BLE. AND SURVEY OR AREA Sec. 3, T-15-S, R-29-E	
14.	. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
_		3852' GL	Chaves New Mexico
16.	Check Ap	propriate Box To Indicate Nature of Notice, Report,	or Other Data

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

WATER SHUT-OFF

(Other)

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

A rig was moved in on Sept. 7th and the casing cut off and 966' pulled. A 30 sx cmt. plug was spotted from 916' to 1016'. Another 30 sx plug was spotted from 193' to 293'. A 5 sx plug was spotted in the top and a steel marker installed. A 9.6# mud laden fluid was used in spotting the plugs.

		Will Farm
18. I hereby certify that the foregoing is true and correct SIGNED	TITLE Vice President Prod.	DATE 9/10/74
(This space for Federal or State office use) ARPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE

9-26-84-11.

Per. Call from Eddie 200, 000 Noble. Ranche complant mr 25 f les. marker down & Reaping" 40 out well head.

Called lin 9:45 Am or Same (P Cinte) also will have one of over enexative of out some.