

Corinne Grace  
STATE # 3  
SECTION 1, T15S, R29E  
CHAVES COUNTY, NEW MEXICO

9/18/74 Drilled and cleaned from 36' to 45' in red clay/  
9/19/74 Drilled and cleaned from 45' to 70' in red clay.  
9/20/74 Drilled and cleaned from 70' to 75' in red clay. 8" hole.  
9/21/74 Tried to get into location and got stuck.  
9/22/74 Tried to get into location and got stuck.  
— 9/23/74 Rained out.  
9/24/74 Tried to get into location and could not due to rain.  
9/25/74 Tried to get into location and could not.  
9/26/74 Working on rig.  
9/27/74 Shut down and waiting for parts.  
9/28/74 Shut down and waiting for parts.  
9/29/74 Shut down and waiting for parts.  
9/30/74 Down on repair.  
10/1/74 Change to a better rig.  
10/2/74 Cleaning up and changing up rigs.  
10/3/74 Cleaning out hole.  
10/4/74 Drilled from 75' to 80' in clay.  
10/5/74 Drilled from 80' to 90' in clay.  
10/6/74 Drilled from 90' to 100' in clay.  
10/7/74 Drilled from 100' to 111' in clay.  
10/8/74 Drilled from 111' to 123' in clay.  
10/9/74 Drilled from 123' to 133' in clay.  
10/10/74 Drilled from 133' to 140' in clay.  
10/11/74 At 140' Lost tools in the hole.  
10/12/74 Fishing