CORTINE GRACE STATE # 3 SECTION 1, T155, R29E CHAVES COUNTY, DEM MEXICO

RECEIVED

MAR 3 1975

CORRECTED REPORT

January 10, 1975

January 11, 1975

January 12, 1975

January 13, 1975

January 31, 1975

February 1, 1975

February 2, 1975

February 3, 1975

February 4, 1975

February 6, 1975

February 7, 1975

February 8, 1975

February 9, 1975

G.C.C. Waiting on orders - Geologist checking samples Vaiting on orders - Geologist checking samples Cleaned out hole - Drilled 3' more to a depth of 1878 Dresser Atlas logged well (Gamma Ray Neutron) Driller Depth 1878 Depth-Logger 1901 Bottom Interval logged 1900 Rigged down and waiting on reverse rig Moved rig in, rigged up, drilled from 1901 to 1902 Waiting on pipe (5¹/₂")

harding on pipe (7

Waiting on casing

Unload casing, strap and get ready to run

Picked up and ran 1383' of $5\frac{1}{2}$ " casing. Cemented with 265 sacks Class"C" w/25 calcium chloride and 2 sacks 20/40sanc Bumped wooden plug at 800#

February 5, 1975 WC cut off pipe rig down halliburton.

Weld on bell nipple, build gas manifold, flange up wellhead

Put on well head pick up 2 7/8 PH6 drilling pipe rig up blow lines. Blow well down

Finish picking up 2 7/8 D.P. Blow well dry Drilled plug and shoe. Clean out 15' of hole.

Cff

February 10, 1975
February 11, 1975
February 11, 1975
February 12, 1975
February 13, 1975
February 13, 1975
Figure stuck in hole. Worked with pipe 16 hours
Rig up wireline service retreive plug. Rig down, Rig up
McCullough. Pull pipe pick up jars and over shot run in hole. Could not get over pipe. Pull out of hole lay down overshot
February 12, 1975
February 13, 1975
February 13, 1975
February 13, 1975
February 13, 1975
February 14, 1975
February 15, 1975
February 16, 1975
February 17, 1975
February 18, 1975
February 19, 1975
Fe