

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instruction  
verse side)

Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM 036718

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Depco - Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

20-15S-28E

12. COUNTY OR PARISH 13. STATE

Chaves

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole JUN 24 1976

2. NAME OF OPERATOR  
Dairmont Oil Corp.

3. ADDRESS OF OPERATOR  
3471 First National Bank Bldg., Dallas, TEXAS 75202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

990' FS & 1650' FRL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3611 g.l.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plugged & abandoned on 5-2-75 at TD 1926 as follows:

70 sx "H" (200') 1926-1726

70 sx "H" (200') 1150-950

70 sx "H" (200') 350-150 (in and out of base of surface)

10 sx at surface

Installed 4' steel marker, cleaned and leveled location.

Ready for inspection.

RECEIVED

SEP - 5 1975

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Geologist

DATE 9-2-75

(This space for Federal or State office use)

TITLE

DATE

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

JUN 22 1976

H. L. BEEKMAN

ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side