UNI D STATES SUBMIT IN TRIPLI (Other Instructions verse side)

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

Form approved. Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

NM-0390241

GEOLOGICAL SURVET	6. IF INDIAN, ALLOTTEE OR TRIBE NAM
TO THE PERMIT OF WELLS	

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

OTICES AND REPOR coposals to drill or to deepen or LICATION FOR PERMIT—" for	plug back the free of reservant proposals.)	re D	7. UNIT AGREEMENT NAM	I E
oration value and Bank Bldg., I soon clearly and in accordance wi	O.C.C. ARTESIA, OFFII Dallas, Texas		8. FARM OR LEASE NAME OWEN-Federa 9. WELL NO. 2 10. FIELD AND POOL, OR SO. LUCKY LI 11. SEC., T., R., M., OR BI SUEVEY OR ARBA	wildcat ake Queer
3860.7	GR		12. COUNTY OR PARISH Chaves Other Data	E 13. STATE NM
	oration value and in accordance with Section 21	NOV 24 19 NOV 24 19 Noration ARTESIA, OFFICATION clearly and in accordance with any State requirements.* Section 21 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3860.7 GR	NOV 24 1975 NOV 24 1975 Paration / ARTESIA. OFFICE 5202 In al Bank Bldg., Dallas, Texas 75202 In clearly and in accordance with any State requirements.* Section 21 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3860.7 GR	NOV 24 1975 8. FARM OR LEASE NAME Owen-Federa Owen-Federa 9. Well NO. 2 10. FIELD AND POOL, OR Section 21 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 17. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Owen-Federa 9. WELL NO. 2 10. FIELD AND POOL, OR SURVEY OR ARBA 21-15-S, 29- 12. COUNTY OR PARISH

(Other) Commenced Operation SHOOT OR ACIDIZE CHANGE PLANS (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) REPAIR WELL 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) •

> Spudded 1:30 P.M. 11/20/75 Cemented 244' - 8 5/8" 20# Casing at 260' with 175 sxs Class C. Lost Circulation at 160'. Filled Annulus with Cement to surface. Plug down 4:30 P.M. W.O.C. 18 hrs. Casing test OK, at 600# S for 30".

> > RECEIVED

NOV 24 1975

U. S. GEOLOGICAL SURVEY ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct	TITLE President	DATE 11/21/75
	TITLE I COI COI	DATE TO THE TOTAL TO THE TOTAL
(This space for Federal or State office use)	TITLE	DATE
NO) 200 AFTEROVAL, IN ANY:		
ACTION DISTRICT ENGINEER *Se	e Instructions on Reverse Side	