

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 15872

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

MARALO, INC.

3. ADDRESS OF OPERATOR

P. O. Box 832, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FNL & 660' FWL, Section 12, T-15-S, R-28-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3681.9 GR

7. UNIT AGREEMENT NAME

Butler Springs Unit

8. FARM OR LEASE NAME

Butler Springs Unit

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 12, T-15-S, R-28-E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On December 1, 1975, ran 1663' 24# & 514' 28# 8-5/8" casing.

Set at 2177'; cemented with 1000 sax Class "H", 10# sand

and .8 of 1% CFR-2. Plug down at 5:00 a.m. December 2,

1975. Did not circulate cement. Ran Temperature Survey -

Top of cement at 800'. After 30 hours pipe tested with

1500# pressure for 30 minutes. Pipe tested okay.

18. I hereby certify that the foregoing is true and correct

SIGNED

Maxima Lamm

TITLE Production Clerk

DATE December 5, 1975

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED
DEC 8 1975
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICOAPPROVED
DEC 8 - 1975
R. L. BEEKMAN
ACTING DISTRICT ENGINEER