

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

JAN 11 1977

O. C. C.

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator  
Yates Petroleum Corporation ✓

3. Address of Operator  
207 South 4th Street - Artesia, NM 88210

4. Location of Well  
UNIT LETTER E 2310 FEET FROM THE North LINE AND 990 FEET FROM  
THE West LINE, SECTION 7 TOWNSHIP 17S RANGE 18E NMPM.

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
K-5999

7. Unit Agreement Name  
Dunken Dome Unit

8. Farm or Lease Name  
Dunken Dome Unit

9. Well No.  
1 2

10. Field and Pool, or Wildcat  
Wildcat Devona

12. County  
Chaves

15. Elevation (Show whether DF, RT, GR, etc.)  
5350' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 18" hole at 3:30 PM 12-7-76. Drilled to 30'. Ran 1 joint of conductor pipe set at 30' GR. Cemented w/4 yards of Ready-mix.

Moved in Rotary Rig and Spudded a 12 1/4" hole at 11:15 PM 12-9-76.

TD 1135' - Ran 27 joints of 8-5/8" 24# K-55 new casing (1135') w/guide shoe, 2 centralizers and 2 baskets at 599' and 757', set at 1135'. Cemented w/175 sacks of Thick-set w/10# gilsonite, 1/4# flocele 2% CaCl. 200 sacks of Halli-Lite w/5# gilsonite, 1/4# flocele 2% CaCl and 100 sacks of Class C 2% CaCl. PD 11:00 AM 12-16-76. Cement did not circulate but could see cement in annulus approx. 120' from surface. WOC 10 hours and filled hole w/5 1/2 yards of Ready-mix. WOC 18 hours, cut off landing joint, nipples up and tested BOB's to 1000#. OK. Reduced hole to 8-3/4", drilled plug and tested to 600#. OK. Resumed drilling.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine Tomlinson TITLE Geol. Secty DATE 1-10-77

APPROVED BY W. A. Gussert TITLE SUPERVISOR, DISTRICT II DATE JAN 12 1977

CONDITIONS OF APPROVAL, IF ANY: