

19th Floor, University Club Building 136 East South Temple Salt Lake City, Utah 84111 Telephone (801) 355-5301

June 1, 1977

Oil Conservation Commission P. O. Drawer DD Artesia, New Mexico

Attention: Mr. W. A. Gressett

Re: Long Canyon Unit #1 Sec. 26, T-19-S, R-19-E Chaves County, New Mexico

Gentlemen:

Enclosed are the following documents relating to subject dry hole which were requested in your letter of May 16, 1977:

- 1. Form C-103 with data on the various strings of casing, cementing, etc., including copies of all cementing reports, a temperature survey on the 8 5/8" casing by Halliburton and an inclination report by Cactus Drilling Co. Also included is a copy of the Hydrostatic Pressure Test of Blowout Control Equipment made by Yellow Jacket Service, Inc.
- 2. Form G103, Notice of Intent to Plug and Abandon
- A copy of Form C-103, Subsequent Report of Plugging and 3. Abandonment, previously sent to you on May 11, 1977.
- 4. Form C-105 Well Completion Report and Log

If there are any questions, please let me know.

Very truly yours,

Earl G. Hoff Manager Production and Engineering

TENE SEC

Enclosures

EGH/dc

cc: U.S. Geological Survey P. O. Drawer "U" Artesia, New Mexico 88210 Son 453 456 1977 Jast Freprise Nel Agiza

shearn steel