

MOUNTAIN STATES PETROLEUM CORPORATION No. 2 Brotar, 20-15S-28E

9. Well site layout:  
See attached diagram.
10. Plans for restoration of surface:  
Cut, dry and level slush pit. Surface is flat caliche mesa. Will restore to present condition. Loose trash will be hauled away.
11. Other information:  
Topography is a flat mesa. Permian Rustler outcrops expose the anhydrite of that formation along with some shales. Thin alkaline caliche soil with scant grass and creosote. Other surface use is primarily grazing-ranching. Previous examination of surface has revealed no artifacts of any type. There are no water wells, ponds or lakes within a one mile radius of well location.
12. Operator's representative:  
K. C. Havenor  
505-623-7184
13. Certification:

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drillsite and access route; that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge, true and correct; and, that the work associated with the operations proposed herein will be performed by Mountain States Petroleum Corporation and its contractors and subcontractors in conformity with this plan and the terms and conditions under which it is approved.

March 28, 1977

  
\_\_\_\_\_  
K. C. Havenor, Geologist