

McCLELLAN OIL CORPORATION MARLISUE NO. 4 ✓
2310' FEL & 2145' FSL Sec. 24-T14S-R29E
Chaves County, New Mexico
State Lease K-6772

Page 2

4/04/79: Prep to install rods and place on pump.
4/05/79: Installing rods and pump.
4/06/79: Pumping load.
4/07/79: Pumping load with a slight show of oil.
4/08/79: Pumping load water.
4/09/79: Pumping load water.
4/10/79: Pumping Load water.
4/11/79: Pumping load water.
4/16/79: Pumping formation water, cut 1% oil. Will test and determine feasibility of continuing to produce.
4/18/79: Prep to place well on tester for 24 hour test.
4/19/79: Tested 24 hours with mechanical tester. Pumped 5 BO, 81 BW. Will continue to pump and test.
4/20/79: Tested 24 hours with mechanical tester - second test. Pumped 4 BO and 79 BW. Well still on tester.
4/23/79: Testing on pump.

RECEIVED

APR 24 1979

O. C. C.
ARTESIA, OFFICE