

STATE	COUNTY	ELEVATION	OWNER	COMPANY	WELL NO.
N Mexico	Chaves	3806 GL	McClellan	McClellan Oil Corporation	
NO OF SAMPLES	LOCATION	S	T	R	FARM
1	2145 ESL & 2310 FEL	24	14-S	29-E	Maslisue State
Tool	DOLO	LIME	SHALE	SAND	CHT.
DEPTH	%	%	Description	%	%
95-1017			100		
36			100		
50			50	50	
75			20	50	
81			10	80	
90			40	60	
1100			60	40	
10			50	50	
21			100		
30			100		
35			90		
50			80		
66			80		
80			90		
99			90		
1212					
25					
46					
52					
60			100		
66			100		
72			100		
80			90	10	
87			10		
92			30		
1301			40		
67			10		
16			10		
26			30		
36			40		
52			20		

JACK L. MCCLELLAN

3807
1199
2608

Yates 1199

30 Vfg sd. - to silt

20 Shaley silt

100 Dk rd. shaley silt - fg unconsol.

90 Shaley sand & silt

70 " "

60 Some fg tile - shaley silt