

N.M.O.C.D. COPY UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-110268

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

N.M.O.-M. Prod. Co.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lake Arthur (Pool)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 25, T-15-S,

R-26-E

12. COUNTY OR PARISH OR STATE

Chaves

NM

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Dry Hole
2. NAME OF OPERATOR
Durham, Inc.
3. ADDRESS OF OPERATOR
219 S. Colorado, Midland, TX 79701
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
660' FSL & 1980' FSL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, ET, GR, etc.)

3401' KB, 3400' DF, 3389' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recore Completion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- Reached TD of 8242' 1230 hrs MDT, 8-12-79.
- Ran DST's and obtained Comp. Dens.-Neutron/GR, FORKO, Guard logs, 8-12-79 through 8-17-79.
- Abandoned well by setting the following plugs: *
Plug #1- 7700'-7850', 45 sx Class H
Plug #2- 5600'-5750', 45 sx Class H
Plug #3- 4300'-4400', 30 sx Class H
Plug #4- 2900'-3000', 30 sx Class H
Plug #5- 1436'-1536', 50 sx Class H
Plug #6- Surface, 10 sx Class H (8-17-79).
No non-drillable material was put in wellbore.
Dry Hole marker installed per applicable State regulation.
Location to be cleaned and restored per Federal guidelines.

* Plugging procedure approved by Mr. Ray Stall, USGS, 1430 hrs MDT, 8-17-79.

18. I hereby certify that the foregoing is true and correct

SIGNED

Les Skinner, P. E.

(This space for Federal or State office use)

TITLE Engineer

DATE 8-23-79

APPROVED BY (Orig. Sgd.) PETER W. CHESTER

TITLE ACTING DISTRICT ENGINEER

DATE OCT 15 1980

CONDITIONS OF APPROVAL, IF ANY: