

McClellan Oil Corporation ✓  
Marlisue #6  
Sec. 24-T14S-R29E  
Chaves County, New Mexico

RECEIVED

APR 28 1980

O. C. D.  
ARTESIA, OFFICE

4/09/80: Moving in Cortez Drilling Company rig No. 258.  
4/10/80: Rigging up.  
4/11/80: Rigging up. Spud later today.  
4/12/80: Spud at 12:30 P.M. 4/11/80. Shut down due to snow.  
4/13/80: Drlg. crooked hole. Filling with rocks and drilling again.  
4/14/80: Drlg. at 92'.  
4/15/80: Drlg. at 135' in red rock. Hole straightened up.  
4/16/80: Drlg. at 250' in red shale.  
4/17/80: Drlg. at 345' in anhydrite and shale. 1½ bailer of water at 280'.  
4/18/80: Drilled to 418'. Running 8-5/8" casing.  
4/19/80: Started up under cement. TD 418'. Drilling, plugging, and cementing. Bailed water.  
4/20/80: Drlg. 515' in salt.  
4/21/80: Drlg. 720' in salt.  
4/22/80: Drlg. at 960' in salt.  
4/23/80: Drlg. at 1140' in anhydrite. 1030' base of salt. 1030' top of anhydrite.  
4/24/80: Drlg. at 1225' in red shale.