6701 Aberdeen Avenue, Suite 9 155 McCutcheon, Suite H Lubbock, Texas 79424 El Paso, Texas 79932 E-Mail: lab@traceanalysis.com

Analytical and Quality Control Report

Hank Jones Eco-Logical Environmental Services 2200 Market Street Midland, TX 79703 Report Date:

June 20, 2002

Order ID Number: A02060513

Project Number:731-1910Project Name:Alto State #2 Clean UpProject Location:Alto State #2 Chavez Co., New Mexico

Enclosed are the Analytical Results and Quality Control Data Reports for the following samples submitted to Trace-Analysis, Inc.

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
198541	Soil Pile #2	Soil	5/24/02	14:15	6/5/02
198542	Soil Pile #3	Soil	5/24/02	14:30	6/5/02
198543	Soil Pile #4	Soil	5/24/02	14:45	6/5/02
198544	Bottom Excavated Pit	Soil	5/24/02	15:15	6/5/02
198545	Location @ Surface	Soil	5/24/02	14:55	6/5/02
198546	Location @ 1' Depth	Soil	5/24/02	15:00	6/5/02
198547	North Wall-Pit	Soil	5/24/02	15:20	6/5/02
198548	West Wall-Pit	Soil	5/24/02	15:30	6/5/02
198549	South Wall-Pit	Soil	5/24/02	15:45	6/5/02
198550	East Wall Pit	Soil	5/24/02	15:55	6/5/02

These results represent only the samples received in the laboratory. The Quality Control Report is generated on a batch basis. All information contained in this report is for the analytical batch(es) in which your sample(s) were analyzed. Note: the RDL is equal to MQL for all organic analytes including TPH.

The test results contained within this report meet all requirements of LAC 33:I unless otherwise noted.

This report consists of a total of 14 pages and shall not be reproduced except in its entirety including the chain of custody (COC), without written approval of TraceAnalysis, Inc.

finich, Director