

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM-068043	
2. NAME OF OPERATOR Read & Stevens, Inc. ✓		6. IF INDIAN, ALLOTTEE OR TRIBE NAME -	
3. ADDRESS OF OPERATOR P.O. Box 1518, Roswell, NM 88201		7. UNIT AGREEMENT NAME -	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990' FWL, 1650' FNL Unit letter E		8. FARM OR LEASE NAME Harris Federal Comm.	
14. PERMIT NO. -		9. WELL NO. 5	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3567.0' GR		10. FIELD AND POOL, OR WILDCAT Buffalo Valley Penn.	
O. C. D. ARTESIA, OFFICE		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25-15S-27E	
		12. COUNTY OR PARISH Chaves	
		13. STATE NM	

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other) Perforate & Treat	☒		

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

4-17-81 Ran 143 jts 2 3/8" tbq, total 293 jts, circ hole w/ 3% KCL water w/ chromate, 9024' to surf.

4-20-81 TIH w/ tbq & Van tool. Ran 284 jts 2 3/8"-4.7# tbq, total 8730.74', 2-8' subs, 1-6' sub & 1-4' sub. 283 jts above pkr 1 jt below pkr, Uni VI pkr set @ 8917'. F nipple @ 8718' w/ 1.87" profile, on-off tool @ 8717'. Dropped bar @ 3:00pm 4-20-81. GTS in 4 min. Gas flowed at 80psi on a 5/8" choke at a rate of 800 MCFPD, perf 8776'-8789' 2 shots/ft.

RECEIVED

APR 22 1981

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *Bruce Stubbins*

TITLE Drilling & Production Mgr. DATE 4-21-81

(This space for Federal approval only)

APPROVED BY *Roger A. Chapman*

CONDITIONS OF APPROVAL

TITLE

DATE

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side