

DRILL STEM TESTS

Date	Formation Tested		Size Choke		Tool		Formation Pressure		oil		water		mud		other		Was Test Satisf
	From	To	Top	Bot	Cushion	Min.	Flowing	S.I.	oil	oil	water	water	mud	mud	other	other	
4-3-50	6077	6144	1	5/8	-	24	150	none					30				yes
4-6-50	6143	6361	1	5/8	-	105	200	none					180				yes
4-28-50	7368	7450	1	5/8	-	60	1350	2500					900				yes
5-7-50	7750	7900	1	5/8	-	60	3175	3225			7084						yes

Hole Deviation: (From 5065') Maximum Dev. 11 deg at 5290' by SYFO.

Administrative Information

Case No.	Date	Time	Location	Status	Remarks	Officer	Signature
100-123456	10/15/2023	14:30	123 Main St, NY	Completed	Investigation of noise complaint.	Officer J. Smith	[Signature]
100-123457	10/15/2023	15:45	456 Elm St, NY	In Progress	Interviewing witnesses regarding traffic accident.	Officer M. Jones	[Signature]
100-123458	10/16/2023	09:00	789 Oak St, NY	Pending	Awaiting forensic analysis of evidence.	Officer K. Brown	[Signature]
100-123459	10/16/2023	11:30	321 Pine St, NY	Completed	Resolution of domestic dispute.	Officer L. Green	[Signature]
100-123460	10/17/2023	16:00	654 Maple St, NY	Open	Continuing investigation of burglary case.	Officer N. White	[Signature]
100-123461	10/17/2023	18:15	987 Cedar St, NY	Completed	Issuance of citation for parking violation.	Officer O. Black	[Signature]
100-123462	10/18/2023	08:45	210 Birch St, NY	In Progress	Conducting surveillance of suspect.	Officer P. Gray	[Signature]
100-123463	10/18/2023	13:20	543 Spruce St, NY	Pending	Waiting for medical report from hospital.	Officer Q. Blue	[Signature]
100-123464	10/19/2023	10:10	876 Willow St, NY	Completed	Successful apprehension of runaway juvenile.	Officer R. Red	[Signature]
100-123465	10/19/2023	14:55	109 Ash St, NY	Open	Investigating suspicious activity in park.	Officer S. Yellow	[Signature]

Report prepared by: [Name] Date: 10/20/2023