



A. R. BROWN  
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office LA 8-0000

Lease No. 8-1-0010

Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 24, 1960

Well No. 1 is located 1930 ft. from N line and 660 ft. from E line of sec. 9

17 (Twp.) 25 (Range) R4P4 (Meridian)  
11000 (Field) ady (County or Subdivision) N. M. (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spotted 15 sack cement plug at 1094 and filled with mud back to 1000' - cut off 5 1/2" csg. at 985' and pulled same - cut 7" csg. at 712' and spotted 100 sack cement plug at 1000' back to 605' - pulled 7" csg. to 270', filled with mud to 270' and spotted 50 sack cement plug - filled with mud to surface and placed further with 5 sack cement.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company C. A. Lewis

Address 191 N. J. Texas

By Carl J. [Signature]

Title Consulting Geologist