

NEW MEXICO OIL CONSERVATION COMMISSION
DRAWER DD
ARTESIA, NEW MEXICO

4.7 ft per sk
in 7"

PLUGGING
FIELD REPORT FOR CEMENTING OF WELLS

Operator <u>M. S. THOMPSON</u>		Lease <u>MORRIS ESTATE</u>		Well # <u>I</u>	
Location of Well	Unit <u>L</u>	Section <u>14</u>	Township <u>17^s</u>	Range <u>25^E</u>	County <u>EDDY</u>
PLUGGING Contractor	<u>Davis well service</u> <u>CAP FULTON</u>		Type of Equipment <u>PULLING UNIT</u>		

APPROVED CASING PROGRAM IN HOLE.

Size of Hole	Size of Casing	Weight Per Foot	New or Used	Depth	Sacks Cement
<u>9 7/8</u>	<u>7</u>	<u>17#</u>	<u>USED</u>	<u>1177</u>	<u>529 TOP Cement 80' BY T.S.</u>
<u>6 1/8</u>	<u>4 1/2</u>	<u>9 1/2#</u>	<u>USED</u>	<u>1166 to 1575</u>	<u>Circulated Rock up into 7"</u>

Casing Data: per 1301 to 1381, 1399 to 1415

Surface joints of inch # Grade
(Approved) (Rejected)

Inspected by date

Cementing Program

Size of hole Size of Casing Sacks cement required

Type of Shoe used Float collar used Btm 3 jts welded

TD of hole 1575 Set Feet of Inch # Grade

New-used csg. @ with sacks neat cement around shoe

 sax additives

Plug down @ (AM) (PM) Date

Cement circulated No. of Sacks

Cemented by Witnessed by

Temp. Survey ran @ (AM) (PM) Date top cement @

Casing test @ (AM) (PM) Date

Method Used Witnessed by

Checked for shut off @ (AM) (PM) Date

Method used PLUGS SPOTTED VIA TUBING Witnessed by LOBLEY 10-1-62

Remarks: TOP SON AND 720' 10-2-62

Plugs as follows.

Hole to be loaded with mud. O.K. 10-1-62

1. 25 sks at T.D. O.K. 10-2-62 Found top plug at 1350'
10 SKS more put in, on this plug. with wire line

2. 20 sks at 700 - O.K. 10-2-62

3. 10 sks in surface of Hole O.K. 10-2-62

Hole loaded with mud before plugging (Blanco clay)