

APPROVED
OCT 25 1963
RONNIE E. SHOOK
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**

Lease No. **02931**

Unit **Saunders**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 17, 19**63**

Well No. **3** is located **330** ft. from **N** line and **990** ft. from **W** line of sec. **13**

NE 1/4 NW 1/4

(1/4 Sec. and Sec. No.)

17S

(Twp.)

27E

(Range)

NMPM

(Meridian)

Empire

(Field)

Eddy

(County or Subdivision)

New Mexico

(State or Territory)

RECEIVED

The elevation of the derrick floor above sea level is _____ ft.

OCT 28 1963

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was completed as a shut in gas well in 1950 and someone put in to plug and abandon by mistake. Please change your records accordingly.

RECEIVED

OCT 23 1963

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

OCT 22 1963

D. C. C.
ARTESIA, OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **R. D. Collier**

Address **Box 798**

Artesia New Mexico

By

Title **Production Clerk**